



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

ORGANIZATION: 51-PASCO COUNTY SCHOOL DISTRICT

FACILITY: SOUTHEAST BUS GARAGE

FACILITY USE: ALL

DISTRICT: 51 PASCO COUNTY SCHOOL DISTRICT

FACILITY: 55-F SOUTHEAST BUS GARAGE

Primary Use: TRANSPORTATION

Grades Housed: DS - DS

DOE Validation Date:

Capital Outlay Classification: ANCILLARY RECOMMENDED FOR CONTINUED USE

MASTER SCHOOL ID

MSID	Name	Status
9001	PASCO DISTRICT OFFICE	Default

CAPITAL OUTLAY FTE

SCHOOL CAPACITY

SCHOOL CAPACITY	YEAR ROUND CAPACITY	UTILIZATION FACTOR	PRIMARY USE
0	0	0.00	TRANSPORTATION



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

PARCEL: 61

37820 13th Avenue

Zephyrhills, FL 33542

Parking: DEVELOPED	Owner: SCHOOL BOARD	Fire: 9
Athletic: NO ATHLETIC FACILITY	Water: PUBLIC	Police: CITY
Sewage: PUBLIC	Plan: COMPACT	Drainage: ADEQUATE
Landscape: PARTIALLY DEVELOPED	Playground: NO PARK/PUBLIC ACCESS	Acreage: 6.00
Date Acquired: 1/1/1980		Lease Expiration Date:

DISTRICT: 51 PASCO COUNTY SCHOOL DISTRICT

FACILITY: 55-F SOUTHEAST BUS GARAGE

BUILDING: 2 - Building Number 00002

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: TRANSPORTATION	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 1980	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1980	Intercom: NONE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	192	419	ANCILLARY FLAMMABLE STORAGE	0	01	CONCRETE	1980	SATISFACTORY	2	61	55



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	192	0	0	0				
TOTAL	192	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 51 PASCO COUNTY SCHOOL DISTRICT

FACILITY: 55-F SOUTHEAST BUS GARAGE

BUILDING: 3 - Building Number 00003

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1985	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1985	Intercom: NONE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	647	421	ANCILLARY STAFF LOUNGE	0	01	COMPOSITION TILE	1985	SATISFACTORY	3	61	55
002	477	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	COMPOSITION TILE	1985	SATISFACTORY	3	61	55
002A	336	401	ANCILLARY CONFERENCE ROOM	0	01	COMPOSITION TILE	1985	SATISFACTORY	3	61	55
003	64	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	COMPOSITION TILE	1985	SATISFACTORY	3	61	55
004	42	825	ANCILLARY RESTROOM (FEMALE)	0	01	CERAMIC TILE	1985	SATISFACTORY	3	61	55
005	42	824	ANCILLARY RESTROOM (MALE)	0	01	CERAMIC TILE	1985	SATISFACTORY	3	61	55

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	1,608	0	0	0				
TOTAL	1,608	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 51 PASCO COUNTY SCHOOL DISTRICT

FACILITY: 55-F SOUTHEAST BUS GARAGE

BUILDING: 4

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2007	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 2007	Intercom: TWO WAY COMPLETE	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
100	2572	592	SCHOOL BUS WORK BAY	0	01	CONCRETE	2007	SATISFACTORY	4	61	55
101	528	585	SCHOOL BUS PARTS ROOM	0	01	CONCRETE	2007	SATISFACTORY	4	61	55
101A	200	426	GENERAL ANCILLARY OFFICE	0	01	CONCRETE	2007	SATISFACTORY	4	61	55
102	120	426	GENERAL ANCILLARY OFFICE	0	01	COMPOSITION TILE	2007	SATISFACTORY	4	61	55
103	8	702	MECHANICAL ROOM	0	01	CONCRETE	2007	SATISFACTORY	4	61	55
104	67	821	STAFF RESTROOM (BOTH SEXES)	0	01	OTHER	2007	SATISFACTORY	4	61	55
105	201	421	ANCILLARY STAFF LOUNGE	0	01	COMPOSITION TILE	2007	SATISFACTORY	4	61	55
106	40	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	2007	SATISFACTORY	4	61	55
107	2156	592	SCHOOL BUS WORK BAY	0	01	CONCRETE	2007	SATISFACTORY	4	61	55
107A	31	703	ELECTRICAL ROOM	0	01	CONCRETE	2007	SATISFACTORY	4	61	55
108	396	591	SCHOOL BUS TIRE STORAGE & MOUNTING	0	01	CONCRETE	2007	SATISFACTORY	4	61	55



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

109	132	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	2007	SATISFACTORY	4	61	55
-----	-----	-----	-----------------------------	---	----	----------	------	--------------	---	----	----

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	6,451	0	0	0				
TOTAL	6,451	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:

FACILITY: SOUTHEAST BUS GARAGE

Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat	Unsat	Satis Rooms			Unsatis Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo	Tot	Tot	Perm	Mod	Relo	Perm	Mod	Relo	Relo	Relo	Relo	Relo
00331	CUSTODIAL SERVICE CLOSET	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00334	CUSTODIAL EQUIPMENT STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00401	ANCILLARY CONFERENCE ROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00407	ANCILLARY ADMINISTRATIVE OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00418	ANCILLARY ADMINISTRATIVE STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00419	ANCILLARY FLAMMABLE STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00421	ANCILLARY STAFF LOUNGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00426	GENERAL ANCILLARY OFFICE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00585	SCHOOL BUS PARTS ROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00591	SCHOOL BUS TIRE STORAGE & MOUNTING	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00592	SCHOOL BUS WORK BAY	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00702	MECHANICAL ROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00703	ELECTRICAL ROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00821	STAFF RESTROOM (BOTH SEXES)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00824	ANCILLARY RESTROOM (MALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00825	ANCILLARY RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
Totals:		0	0	0	0	0	0	0	0	19	0	0	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT
